

15.4.21 Lack phase failure of outdoor DC fan motor(EC 72)

