


15.4.22 Outdoor compressor lack phase protection(PC 43)



15.4.23 Outdoor unit IR chip drive failure(PC45)

