

Error Code: EH C3 – Refrigerant Sensor Out of Range

Applies to LETO and AURA Series

What this means:

The indoor unit is not receiving valid feedback from the refrigerant sensor. This could mean the sensor is disconnected, malfunctioning, or reporting values outside its expected range.

Try this first (easy fix):

1. Turn off power to your mini split completely.
 2. Wait 2 full minutes.
 3. Turn the power back on and check if the error clears.
- If the error clears — you're good to go.
 - If the error is still there — move to the next steps.

Next steps (for technicians):

- Check the wiring between the refrigerant sensor and the indoor PCB.
- Confirm that all connections are secure and properly seated.
- If the wiring is good:
 - Replace the refrigerant sensor.
 - If the error still exists after that, replace the indoor main PCB.

What you might need:

- Refrigerant sensor
- Indoor main PCB
- Connection wires

Helpful tip:

This error typically occurs when feedback from the sensor is missing for over 150 seconds, or when a fault signal is received continuously for 10 seconds. Always check wiring first before replacing any parts.